
角焊接规

969

- ◆ 标配纸卡
- ◆ 不锈钢材料







测量焊缝高度Η和角度θ,根据Η和θ计算出焊缝计 算厚度t_e和理论焊脚尺寸L

货号	测量项目	量程	分度值	精度
969-050-01	焊缝高度 H	0-50mm/0-2"	2mm/.050"	±1mm
	角度 θ	30°- 90°	2.5°	±1°
	60°角	_	_	±0.5°



